

Mercedes-Benz Actros 3340 6x6 Kanalreinigung + Wasserrückgewinner

General characteristics

Brand	Mercedes-Benz
Model	Actros 3340
Subcategory	Vacuum truck
Meter reading	200.958km
Year of construction	1999
Date of first registration	28-10-1999
Colour	Orange
Condition	Used
General state	Good
Fuel	Diesel
Emission class	Euro 2
Reference	Mercedes Actros 3340 6x6 Kolkenzuiger 1999



Mercedes-Benz Actros 3340 6x6 Kanalreinigung + Wasserrückgewinner

Technical specifications

Number of axes	3
Axis configuration	6x6
Transmission	Semi-automatic
Assets	400hp

Description

6x6 Teligent transmission, 3 pedals Assmann sewer cleaning system with water recovery made of V2A stainless steel Uraca high-pressure pump, 135 bar 120 m cleaning hose Sterling water recovery pump 15 m suction hose In good condition Ready for work

Accessories

- Air conditioning
- Aluminium fuel tank
- Leaf spring suspension
- Electrically operated windows
- Xenon lighting
- Visor